

Buildings By Year

- Before 1964** (service line and internal fittings may contain more than 8% lead)
- 1964 - 1998** (internal fittings may contain more than 8% lead)
- 1999 - 2014** (internal fittings have less than 8% lead, solder has less than 0.2%)
- 2015 - Present** (internal fittings have less than 0.25% lead)
- Known Lead Service**
- Water Operational Area**
- Water Mains**

